



## 交通部航港局航船布告

中華民國 113 年 1 月 17 日

**31** 礙航公告（北區）基隆籍「勇豐餘」漁船（CT4-2038）於龜山島海域失火，漁船殘骸海上漂流，目前位置烏石港外1浬（經緯度N24度51分、E121度51分）。

依據 海巡署艦隊分署第七岸巡隊 113 年 1 月 17 日航船布告傳真通報。  
說明 1、基隆籍「勇豐餘」漁船（CT4-2038）於龜山島海域（N24度52分，E121度54分）失火，船上2人已救離，漁船殘骸海上漂流，**目前位置**已漂流至烏石港外1浬（N24度51分、E121度51分）。

2、請過往船舶注意瞭望及避讓，以維航行安全。

3、位置：北緯 24°51'，東經 121°51'。

位置 北緯 24°51'00.0"，東經 121°51'00.0"。\*WGS84

交通部航港局  
局長 葉協隆



## NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

---

January 17, 2024

**31** The fishing vessel "Yong Fengyu" (CT4-2038) caught fire near Guishan Island (N 24°52', E 121°54'), and drifted to 1 mile outside Wushi Port in Yilan County (N 24°51', E 121°51').

Source It shall be handled in accordance with the fax notice of the Seventh Coast Patrol of the Fleet Branch of the Coast Guard on January 17, 2024.

Details 1.The Keelung-registered fishing boat "Yong Fengyu" (CT4-2038) caught fire in the waters off Guishan Island□24°52'N□121°54'E□, 2 people on board have been rescued, and the wreckage of the fishing boat has drifted to the sea and has drifted to 1 mile outside Wushi Port□24°51'N□121°51'E□.

2.Passing ships are advised to pay attention to lookout and avoid to maintain navigation safety.

3.Position: 24°51' N, 121°51' E.

Positions Lat. 24°51'00.0" N., Long. 121°51'00.0" E. \*WGS84

*Maritime and Port Bureau, MOTC  
Director-General Yeh Hsieh-Lung*