



交通部航港局航船布告

中華民國 114 年 5 月 27 日

257 礙航公告(中區)(至114年8月22日)麥寮工業區專用港管理股份有限公司「麥寮港域及航道浚挖維護」

依據 麥寮工業區專用港管理股份有限公司 114 年 5 月 20 日麥寮專港字第 1140004 896 號函。

說明 旨揭公司自 114 年 5 月 26 日至 114 年 8 月 22 日進行麥寮港域及航道浚挖維護工程作業。

航行船隻，請避開該區域，注意航行以策安全。

位置 北緯 23°46'18.7"，東經 120°08'18.5"。
北緯 23°45'55.4"，東經 120°08'35.6"。
北緯 23°46'32.6"，東經 120°09'34.4"。
北緯 23°46'37.1"，東經 120°09'37.8"。
北緯 23°46'46.2"，東經 120°09'35.7"。
北緯 23°46'57.8"，東經 120°09'44.0"。
北緯 23°46'50.9"，東經 120°09'51.5"。
北緯 23°46'31.5"，東經 120°09'52.0"。
北緯 23°46'20.8"，東經 120°10'14.7"。
北緯 23°47'51.5"，東經 120°11'04.2"。
北緯 23°47'58.5"，東經 120°10'30.4"。
北緯 23°47'31.6"，東經 120°09'58.4"。
北緯 23°47'10.7"，東經 120°09'40.8"。
北緯 23°47'00.0"，東經 120°08'46.0"。
北緯 23°46'47.7"，東經 120°08'55.0"。
北緯 23°47'11.3"，東經 120°09'32.5"。
北緯 23°47'23.6"，東經 120°09'23.4"。
北緯 23°45'25.6"，東經 120°08'47.0"。
北緯 23°45'21.3"，東經 120°08'43.7"。
北緯 23°45'11.3"，東經 120°08'35.5"。
北緯 23°45'00.5"，東經 120°08'31.5"。
北緯 23°44'41.7"，東經 120°08'24.0"。
北緯 23°44'15.4"，東經 120°08'17.0"。
北緯 23°43'50.1"，東經 120°08'10.0"。
北緯 23°43'46.2"，東經 120°08'33.0"。
北緯 23°44'20.6"，東經 120°08'38.3"。
北緯 23°44'36.7"，東經 120°08'43.2"。
北緯 23°44'51.8"，東經 120°08'55.2"。
北緯 23°45'13.1"，東經 120°08'59.0"。
北緯 23°45'26.1"，東經 120°08'54.8"。*WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

May 27, 2025

257

Mailiao Industrial Harbor-Dredging Operations

Source

Mailiao Harbor Administration Corp., No. 1140004896 dated May 20th, 2025.

Details

Maintenance dredging operations will be carried out at Mailiao Industrial Harbor and be expected to complete at August 22nd, 2025.

Mariners are advised to navigate with caution in the area.

Positions

Lat. 23°46'18.7" N., Long. 120°08'18.5" E.
Lat. 23°45'55.4" N., Long. 120°08'35.6" E.
Lat. 23°46'32.6" N., Long. 120°09'34.4" E.
Lat. 23°46'37.1" N., Long. 120°09'37.8" E.
Lat. 23°46'46.2" N., Long. 120°09'35.7" E.
Lat. 23°46'57.8" N., Long. 120°09'44.0" E.
Lat. 23°46'50.9" N., Long. 120°09'51.5" E.
Lat. 23°46'31.5" N., Long. 120°09'52.0" E.
Lat. 23°46'20.8" N., Long. 120°10'14.7" E.
Lat. 23°47'51.5" N., Long. 120°11'04.2" E.
Lat. 23°47'58.5" N., Long. 120°10'30.4" E.
Lat. 23°47'31.6" N., Long. 120°09'58.4" E.
Lat. 23°47'10.7" N., Long. 120°09'40.8" E.
Lat. 23°47'00.0" N., Long. 120°08'46.0" E.
Lat. 23°46'47.7" N., Long. 120°08'55.0" E.
Lat. 23°47'11.3" N., Long. 120°09'32.5" E.
Lat. 23°47'23.6" N., Long. 120°09'23.4" E.
Lat. 23°45'25.6" N., Long. 120°08'47.0" E.
Lat. 23°45'21.3" N., Long. 120°08'43.7" E.
Lat. 23°45'11.3" N., Long. 120°08'35.5" E.
Lat. 23°45'00.5" N., Long. 120°08'31.5" E.
Lat. 23°44'41.7" N., Long. 120°08'24.0" E.
Lat. 23°44'15.4" N., Long. 120°08'17.0" E.
Lat. 23°43'50.1" N., Long. 120°08'10.0" E.
Lat. 23°43'46.2" N., Long. 120°08'33.0" E.
Lat. 23°44'20.6" N., Long. 120°08'38.3" E.
Lat. 23°44'36.7" N., Long. 120°08'43.2" E.
Lat. 23°44'51.8" N., Long. 120°08'55.2" E.
Lat. 23°45'13.1" N., Long. 120°08'59.0" E.
Lat. 23°45'26.1" N., Long. 120°08'54.8" E. *WGS84

Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC