



交通部航港局航船布告

中華民國 112 年 7 月 5 日

381 礙航公告(中區)(112年7月12日至112年7月13日)彰化離岸風場航道船舶交通服務系統(VTS)規劃與建置案之設備更新作業

依據 彰化離岸風場航道船舶交通服務系統(VTS)規劃與建置案之設備遷移作業。

說明 配合彰化離岸風場航道 VTS 中心設備更新，請 112 年 7 月 12 至 13 日間行經彰化風場航道之船舶倘遇無線電收訊不佳狀況，請稍後補報到程序；另該段期間內航道船舶如遇緊急情況事故須通報聯繫者，倘遇 VTS 收訊不佳請轉呼叫基隆海岸電臺協助。

位置 北緯 24°09'57.6"，東經 120°12'25.2"。
北緯 24°08'31.2"，東經 120°09'00.0"。
北緯 23°57'25.2"，東經 120°00'21.6"。
北緯 23°52'58.8"，東經 119°59'13.2"。
北緯 23°54'46.8"，東經 119°55'37.2"。
北緯 24°12'25.2"，東經 120°09'14.4"。
北緯 24°13'04.8"，東經 120°08'24.0"。
北緯 23°55'19.2"，東經 119°54'39.6"。
北緯 23°56'16.8"，東經 119°52'44.4"。
北緯 24°14'20.4"，東經 120°06'43.2"。
北緯 24°12'25.2"，東經 120°09'14.4"。
北緯 23°54'46.8"，東經 119°55'37.2"。
北緯 23°55'19.2"，東經 119°54'39.6"。
北緯 24°13'04.8"，東經 120°08'24.0"。
北緯 24°07'15.6"，東經 120°11'16.8"。
北緯 23°56'24.0"，東經 120°02'52.8"。
北緯 23°52'19.2"，東經 120°01'51.6"。
北緯 23°52'58.8"，東經 119°59'13.2"。
北緯 23°57'25.2"，東經 120°00'21.6"。
北緯 24°08'31.2"，東經 119°09'00.0"。
北緯 24°09'57.6"，東經 120°12'25.2"。
北緯 24°14'20.4"，東經 120°06'43.2"。
北緯 23°56'16.8"，東經 119°52'44.4"。
北緯 23°57'00.0"，東經 119°51'18.0"。
北緯 24°15'21.6"，東經 120°05'27.6"。*WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

July 5, 2023

381 Upgrading and Migrating Reporting Systems of Changhua VTS

Source Migrating Reporting Systems of Changhua VTS.

Details Reporting systems of Changhua Wind Farm Channel will be upgraded and migrated from July 12th to July 13th. Please report to VTS center on pre-arrival later if poor radio reception happened.

Notify Keelung Radio if urgent accident occurred during the upgrading and migrating work.

Positions Lat. 24°09'57.6" N., Long. 120°12'25.2" E.
Lat. 24°08'31.2" N., Long. 120°09'00.0" E.
Lat. 23°57'25.2" N., Long. 120°00'21.6" E.
Lat. 23°52'58.8" N., Long. 119°59'13.2" E.
Lat. 23°54'46.8" N., Long. 119°55'37.2" E.
Lat. 24°12'25.2" N., Long. 120°09'14.4" E.
Lat. 24°13'04.8" N., Long. 120°08'24.0" E.
Lat. 23°55'19.2" N., Long. 119°54'39.6" E.
Lat. 23°56'16.8" N., Long. 119°52'44.4" E.
Lat. 24°14'20.4" N., Long. 120°06'43.2" E.
Lat. 24°12'25.2" N., Long. 120°09'14.4" E.
Lat. 23°54'46.8" N., Long. 119°55'37.2" E.
Lat. 23°55'19.2" N., Long. 119°54'39.6" E.
Lat. 24°13'04.8" N., Long. 120°08'24.0" E.
Lat. 24°07'15.6" N., Long. 120°11'16.8" E.
Lat. 23°56'24.0" N., Long. 120°02'52.8" E.
Lat. 23°52'19.2" N., Long. 120°01'51.6" E.
Lat. 23°52'58.8" N., Long. 119°59'13.2" E.
Lat. 23°57'25.2" N., Long. 120°00'21.6" E.
Lat. 24°08'31.2" N., Long. 119°09'00.0" E.
Lat. 24°09'57.6" N., Long. 120°12'25.2" E.
Lat. 24°14'20.4" N., Long. 120°06'43.2" E.
Lat. 23°56'16.8" N., Long. 119°52'44.4" E.
Lat. 23°57'00.0" N., Long. 119°51'18.0" E.
Lat. 24°15'21.6" N., Long. 120°05'27.6" E. *WGS84

*Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung*