



交通部航港局航船布告

中華民國 113 年 3 月 5 日

103

礙航公告(中區)(即日起至113年9月14日)海龍二號及海龍三號風電股份有限公司「海龍二號暨海龍三號離岸風力發電計畫執行風場內戒護作業」

依據 海龍二號風電股份有限公司 113 年 3 月 4 日海二電字第 2024030401 號函及
海龍三號風電股份有限公司 113 年 3 月 4 日海三電字第 2024030401 號函。
說明 旨揭風場即日起至 113 年 9 月 14 日止進行戒護作業，非計畫相關之工作船
隻請避開該區域，注意航行以策安全，相關資料詳如附件。
位置 北緯 23°58'08.4"，東經 119°48'49.7"。
北緯 24°02'38.4"，東經 119°51'26.3"。
北緯 24°02'40.2"，東經 119°55'40.1"。
北緯 23°57'01.4"，東經 119°51'18.7"。
北緯 24°02'33.0"，東經 119°40'53.4"。
北緯 24°01'49.4"，東經 119°40'34.7"。
北緯 23°58'08.4"，東經 119°48'49.7"。
北緯 24°02'38.4"，東經 119°51'26.3"。*WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

March 5, 2024

103 Changhua Taiwan Offshore-Hai Long 2 and Hai Long 3 Offshore Wind Farm
Guard Vessels Details

Source Hai Long 2 Offshore Wind Power Co., Ltd, letter No. 2024030401 dated March 4, 2024.

Hai Long 3 Offshore Wind Power Co., Ltd, letter No. 2024030401 dated March 4, 2024.

Details Tug boats and fishing boats shall be supporting Hai Long 2 and Hai Long 3 Offshore Wind Farm to monitor the wind farm sites as deemed required until September 14, 2024.

Mariners are advised to navigate with caution in the area.

Please refer to the attachment for more details.

Positions Lat. 23°58'08.4" N., Long. 119°48'49.7" E.

Lat. 24°02'38.4" N., Long. 119°51'26.3" E.

Lat. 24°02'40.2" N., Long. 119°55'40.1" E.

Lat. 23°57'01.4" N., Long. 119°51'18.7" E.

Lat. 24°02'33.0" N., Long. 119°40'53.4" E.

Lat. 24°01'49.4" N., Long. 119°40'34.7" E.

Lat. 23°58'08.4" N., Long. 119°48'49.7" E.

Lat. 24°02'38.4" N., Long. 119°51'26.3" E. *WGS84

Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC