



交通部航港局航船布告

中華民國 114 年 8 月 1 日

436

射擊公告(北中南東區)空軍114年9月份實彈射擊報告單

依據 國防部空軍司令部 114 年 7 月 30 日國空戰整字第 1140180525 號函
說明 一、射擊區域及時間：詳細資訊請參閱附件

二、航行船隻，請避開射擊危險區域，注意航行以策安全。

三、請至航港局局網「訊息發布」-「航船布告」-「全部」(<https://www.motcmpb.gov.tw/Information/Notice?SiteId=1&NodeId=483>)，建議隨時瀏覽，預為規劃。

位置 北緯 23°18'18.0"，東經 119°20'33.0"。
北緯 25°48'00.0"，東經 120°48'00.0"。
北緯 25°48'00.0"，東經 121°20'00.0"。
北緯 24°52'00.0"，東經 120°23'00.0"。
北緯 24°52'00.0"，東經 119°55'00.0"。
北緯 24°48'00.0"，東經 119°50'00.0"。
北緯 24°48'00.0"，東經 120°20'00.0"。
北緯 23°55'00.0"，東經 119°27'00.0"。
北緯 24°10'00.0"，東經 119°08'00.0"。
北緯 22°34'00.0"，東經 118°55'00.0"。
北緯 22°59'00.0"，東經 119°39'00.0"。
北緯 22°16'00.0"，東經 119°37'00.0"。
北緯 22°21'00.0"，東經 118°55'00.0"。
北緯 23°43'00.0"，東經 122°05'00.0"。
北緯 23°43'00.0"，東經 122°38'00.0"。
北緯 23°20'00.0"，東經 122°38'00.0"。
北緯 23°00'00.0"，東經 122°05'00.0"。
北緯 23°29'54.0"，東經 120°07'59.0"。
北緯 22°14'53.0"，東經 121°40'29.0"。
北緯 22°26'53.0"，東經 122°00'29.0"。
北緯 21°32'53.0"，東經 122°00'29.0"。
北緯 21°41'53.0"，東經 121°40'29.0"。*WGS84

海圖 普通海圖第 0001, 00011, 0001A(四), 00051, 00013, 00014, 0307, 0312, 0313, 0319, 0328B, 0331, 0336, 04528, 0471, 0479, 0001A(二), 00041, 0106, 0306, 0314, 0328A, 0356, 1492, 04507, 0343, 0471B, 0352, 0338, 04524 號。
電子海圖第 1U319230, 1U320250, 1U321250, 1U320240, 1U319240, 1U318220, 1U319220, 1U322230, 1U322220, 1U320230, 1U321220, 1U322210, 1U321210, 1U419230, 1U421251, 1U420241, 1U419243, 1U419231, 1U419223, 1U419222, 1U422231, 1U422221, 1U420230, 1U421222, 1U422220, 1U422211, 1U421213, 1U421250, 1U420252, 1U420243, 1U419233, 1U420240, 1U419242, 1U419240, 1U419221, 1U419220, 1U422230 號。



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

August 1, 2025

436 Taiwan Around Waters-Military exercise(RESTRICTED AREA
NO.7□9□11□12□17□38□42)

Source Air Force Command Headquarter, MND, letter No.1140180525 dated Jul 30,
2025

Details 1.Military exercise will be undertaken on Sep. 1-2□4-5□8-12□15-19□22-26□30
, 2025.
2.During the exercise period, all vessels are prohibited from sailing the exercise w
aters.

Positions Lat. 23°18'18.0" N., Long. 119°20'33.0" E.
Lat. 25°48'00.0" N., Long. 120°48'00.0" E.
Lat. 25°48'00.0" N., Long. 121°20'00.0" E.
Lat. 24°52'00.0" N., Long. 120°23'00.0" E.
Lat. 24°52'00.0" N., Long. 119°55'00.0" E.
Lat. 24°48'00.0" N., Long. 119°50'00.0" E.
Lat. 24°48'00.0" N., Long. 120°20'00.0" E.
Lat. 23°55'00.0" N., Long. 119°27'00.0" E.
Lat. 24°10'00.0" N., Long. 119°08'00.0" E.
Lat. 22°34'00.0" N., Long. 118°55'00.0" E.
Lat. 22°59'00.0" N., Long. 119°39'00.0" E.
Lat. 22°16'00.0" N., Long. 119°37'00.0" E.
Lat. 22°21'00.0" N., Long. 118°55'00.0" E.
Lat. 23°43'00.0" N., Long. 122°05'00.0" E.
Lat. 23°43'00.0" N., Long. 122°38'00.0" E.
Lat. 23°20'00.0" N., Long. 122°38'00.0" E.
Lat. 23°00'00.0" N., Long. 122°05'00.0" E.
Lat. 23°29'54.0" N., Long. 120°07'59.0" E.
Lat. 22°14'53.0" N., Long. 121°40'29.0" E.
Lat. 22°26'53.0" N., Long. 122°00'29.0" E.
Lat. 21°32'53.0" N., Long. 122°00'29.0" E.
Lat. 21°41'53.0" N., Long. 121°40'29.0" E. *WGS84

Chart affected NMOO Charts 0001, 00011, 0001A(四), 00051, 00013, 00014, 0307, 0312, 0313,
0319, 0328B, 0331, 0336, 04528, 0471, 0479, 0001A(二), 00041, 0106, 0306, 03
14, 0328A, 0356, 1492, 04507, 0343, 0471B, 0352, 0338, 04524.
ENC 1U319230, 1U320250, 1U321250, 1U320240, 1U319240, 1U318220, 1U31
9220, 1U322230, 1U322220, 1U320230, 1U321220, 1U322210, 1U321210, 1U4
19230, 1U421251, 1U420241, 1U419243, 1U419231, 1U419223, 1U419222, 1U
422231, 1U422221, 1U420230, 1U421222, 1U422220, 1U422211, 1U421213, 1
U421250, 1U420252, 1U420243, 1U419233, 1U420240, 1U419242, 1U419240,
1U419221, 1U419220, 1U422230.

Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung

