



交通部航港局航船布告

中華民國 115 年 4 月 13 日

198 礙航公告(中區)(更新編號第20260155號布告)(至119年10月18日)
)彰芳暨西島離岸風場之風場維護更新船舶資訊

依據 彰芳風力發電股份有限公司 115 年 4 月 10 日彰芳風力字第 1150410002 號
說明 1. 旨述風場維護工作作業期間至 2030 年 10 月 18 日，新增船舶汐威奔馳(C
Wind Phoenix)執行風場運維工作。

2. 非旨述計畫相關之工作船隻請避開該區域，注意航行以策安全，相關資料詳如附件。

位置 北緯 24°02'14.3"，東經 120°07'02.0"。
北緯 24°02'21.3"，東經 120°09'13.5"。
北緯 24°02'18.0"，東經 120°11'31.5"。
北緯 23°59'52.2"，東經 120°10'46.2"。
北緯 23°58'00.5"，東經 120°08'24.6"。
北緯 23°58'14.4"，東經 120°05'06.5"。
北緯 24°00'09.6"，東經 120°05'25.4"。
北緯 23°58'01.5"，東經 120°12'04.2"。
北緯 23°56'49.3"，東經 120°10'57.3"。*WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

April 13, 2026

198

Chang Fang Wind Power Co Update maintenance activity ship information

Source

Chang Fang Wind Power Co. No.1150410002 dated April 10, 2026.

Details

1. The wind farm maintenance work is scheduled to continue until October 18, 2030. The newly added vessels CWind Phoenix will be responsible for wind farm operation and maintenance.

2. Vessels not involved in the planned work should avoid this area and exercise caution when navigating. Details are attached.

Positions

Lat. 24°02'14.3" N., Long. 120°07'02.0" E.

Lat. 24°02'21.3" N., Long. 120°09'13.5" E.

Lat. 24°02'18.0" N., Long. 120°11'31.5" E.

Lat. 23°59'52.2" N., Long. 120°10'46.2" E.

Lat. 23°58'00.5" N., Long. 120°08'24.6" E.

Lat. 23°58'14.4" N., Long. 120°05'06.5" E.

Lat. 24°00'09.6" N., Long. 120°05'25.4" E.

Lat. 23°58'01.5" N., Long. 120°12'04.2" E.

Lat. 23°56'49.3" N., Long. 120°10'57.3" E. *WGS84

*Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung*