



## 交通部航港局航船布告

中華民國 115 年 7 月 1 日

|          |                                                                                                                                                                                                                                                                                                                |
|----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 20260377 | 航標公告(全區)交通部中央氣象署115年7至9月進行彭佳嶼等6站海氣象資料浮標及2站水位浮標站新品重新布放及舊品回收                                                                                                                                                                                                                                                     |
| 依 據      | 交通部中央氣象署115年6月30日中象海字第1150008191號函                                                                                                                                                                                                                                                                             |
| 說 明      | <p>一、海氣象資料浮標(彭佳嶼、馬祖、富貴角、花蓮、新竹、小琉球6站):</p> <ol style="list-style-type: none"><li>1.浮標本體為直徑2.6至2.9公尺黃色三角錐狀鋁合金體。</li><li>2.夜間警示裝置：黃色閃光燈，每4秒閃一次。</li></ol> <p>二、水位浮標-臺南、新竹2站</p> <ol style="list-style-type: none"><li>1.浮標本體為直徑1.5公尺黃色圓碟型鋁合金體</li><li>2.夜間警示裝置：黃色閃光燈，每4秒閃一次。</li></ol> <p>三、航行船隻請注意瞭望，以維航行安全。</p> |
| 位 置      | <p>新竹水位浮標</p> <p>(J1) 北緯 24°45'19"，東經 120°52'03"</p> <p>(J2) 北緯 24°45'22"，東經 120°52'08"</p> <p>臺南水位浮標</p> <p>(I1) 北緯 22°58'37"，東經 120°08'12"</p> <p>(I2) 北緯 22°58'38.6"，東經 120°08'12.8"</p> <p>小琉球資料浮標</p> <p>(H1) 北緯 22°19'02"，東經 120°22'33"</p> <p>(H2) 北緯 22°19'02"，東經 120°22'41"</p>                       |

新竹資料浮標

(G1) 北緯  $24^{\circ}45'46''$ , 東經  $120^{\circ}50'35''$

(G2) 北緯  $24^{\circ}45'48''$ , 東經  $120^{\circ}50'41''$

花蓮資料浮標

(F1) 北緯  $24^{\circ}01'53''$ , 東經  $121^{\circ}37'57''$

(F2) 北緯  $24^{\circ}01'55''$ , 東經  $121^{\circ}37'55''$

富貴角資料浮標

(E1) 北緯  $25^{\circ}18'14''$ , 東經  $121^{\circ}32'00''$

(E2) 北緯  $25^{\circ}18'13''$ , 東經  $121^{\circ}31'52''$

馬祖資料浮標

(D1) 北緯  $26^{\circ}21'16''$ , 東經  $120^{\circ}30'45''$

(D2) 北緯  $26^{\circ}21'19''$ , 東經  $120^{\circ}30'49''$

彭佳嶼資料浮標

(C1) 北緯  $25^{\circ}37'17''$ , 東經  $122^{\circ}03'58''$

(C2) 北緯  $25^{\circ}37'14''$ , 東經  $122^{\circ}04'02''$

交通部航港局  
局長 葉協隆



## NOTICE TO MARINERS Published by Maritime Port Bureau, MOTC, R.O.C.

---

July 01, 2026

|          |                                                                                                                                                                                                                                                                                                                                       |
|----------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 20260377 | Taiwan waters-Recovery and redeployment of weather data buoys and water level buoys in Taiwanese waters                                                                                                                                                                                                                               |
| Source   | Central Weather Administration, Letter No.1150008191 dated June 30, 2026                                                                                                                                                                                                                                                              |
| Details  | Maritime Buoys(Weather data buoys 、 Water level buoy) had been deployed at the following position.<br>Mariners are advised to navigate with caution in the area.                                                                                                                                                                      |
| Position | 新竹水位浮標<br>(J1) N 24°45'19", E 120°52'03"<br>(J2) N 24°45'22", E 120°52'08"<br><br>臺南水位浮標<br>(I1) N 22°58'37", E 120°08'12"<br>(I2) N 22°58'38.6", E 120°08'12.8"<br><br>小琉球資料浮標<br>(H1) N 22°19'02", E 120°22'33"<br>(H2) N 22°19'02", E 120°22'41"<br><br>新竹資料浮標<br>(G1) N 24°45'46", E 120°50'35"<br>(G2) N 24°45'48", E 120°50'41" |

花蓮資料浮標

(F1) N 24°01'53", E 121°37'57"

(F2) N 24°01'55", E 121°37'55"

富貴角資料浮標

(E1) N 25°18'14", E 121°32'00"

(E2) N 25°18'13", E 121°31'52"

馬祖資料浮標

(D1) N 26°21'16", E 120°30'45"

(D2) N 26°21'19", E 120°30'49"

彭佳嶼資料浮標

(C1) N 25°37'17", E 122°03'58"

(C2) N 25°37'14", E 122°04'02"

Maritime and Port Bureau, MOTC  
Director General Yeh Hsieh-Lung