



## 交通部航港局航船布告

中華民國 112 年 6 月 12 日

### 317 礙航公告(中區)允能風力發電股份有限公司「雲林風場水下基礎閃光浮標通告」

依據 允能風力發電股份有限公司 112 年 6 月 8 日允字第 112060801 號函。  
說明 旨揭公司編號 YUN06 單樁式水下基礎由於不明原因未能成功打設，該單樁頂端目前位於海平面下，位置座標為北緯 23 度 39 分 11.187 秒；東經 120 度 3 分 58.783 秒。

前揭單樁位置周圍以 3 座閃光浮標圍繞標示，燈質為白色閃光週期為三秒，以利過往船隻辨識並避讓。浮標位置說明如下：

A：23°39'13.14"N；120°3'55.08"E

B：23°39'13.08"N；120°4'2.4"E

C：23°39'7.26"N；120°3'59.28"E

航行船隻，請避開該區域，注意航行以策安全。  
位置 北緯 23°39'13.1"，東經 120°03'55.1"。  
北緯 23°39'13.1"，東經 120°04'02.4"。  
北緯 23°39'07.3"，東經 120°03'59.3"。\*WGS84

交通部航港局  
局長 葉協隆



## NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

---

June 12, 2023

**317**

Yunlin Taiwan Offshore – Deployment of special mark buoys.

Source

Yunneng Wind Power Co., Ltd., letter No. 112060801, dated June 8, 2023.

Details

Due to unknown reason, one mono pile YUN06 did not succeed to complete.( 23° 39' 11.187" N□120° 3' 58.783" E)

The top of YUN06 mono pile is under the mean water level. This position was marked with 3 buoys in below positions. Buoys are white, with green Hi-vis stripes.

Lights flash white every 3 sec.

A: 23°39'13.14"N□120°3'55.08"E

B: 23°39'13.08"N□120°4'2.4"E

C: 23°39'7.26"N□120°3'59.28"E

Mariners are advised to navigate with caution in the area.

Positions

Lat. 23°39'13.1" N., Long. 120°03'55.1" E.

Lat. 23°39'13.1" N., Long. 120°04'02.4" E.

Lat. 23°39'07.3" N., Long. 120°03'59.3" E. \*WGS84

*Maritime and Port Bureau, MOTC  
Director-General Yeh Hsieh-Lung*