



交通部航港局航船布告

中華民國 112 年 7 月 5 日

378

礙航公告(中區)(112年7月7日至112年10月31日)海能風力發電股份有限公司「海能風場陣列電纜維修」相關資訊

依據 海能風力發電股份有限公司 112 年 7 月 4 日能 T 字第 2023072317 號函。
說明 旨揭電纜維修作業委由比利時商楊德諾有限公司以威廉 (WILLEM DE VLA MINGH)、臺港 13206 號 (TIPM NO.13206) 及臺港 22605 號 (TIPM No. 2260 5) 自 112 年 7 月 7 日至 112 年 10 月 31 日執行 B11 與 B12 風力發電機之間陣列海纜維修工作。

非計畫相關之工作船隻，請避開該區域，注意航行以策安全，相關資料詳如附件。

位置 北緯 24°46'27.1"，東經 120°47'31.6"。
北緯 24°46'58.4"，東經 120°48'02.5"。*WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

July 5, 2023

378 Miaoli Taiwan Offshore-Formosa 2 Offshore Wind Farm Subsea Cable Maintenance and Repair

Source Formosa 2 Offshore Wind Farm, letter No. 2023072317 dated July 4, 2023.
Details Cable maintenance and repair work between WTG B11 and B12 within Formosa 2 Offshore Wind Farm will be conducted from July 7th to October 31st, 2023. Vessels involved in the operation are as follows: Willem de Vlamingh(Cable Laying Vessel), TIPM-13206(Guard Vessel) and TIPM-22605(Crew Transfer Vessel). Mariners are advised to navigate with caution in the area. Please refer to the attachment for more details.
Positions Lat. 24°46'27.1" N., Long. 120°47'31.6" E.
Lat. 24°46'58.4" N., Long. 120°48'02.5" E. *WGS84

Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung